

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/31/2022

Submitted Date:

05/31/2022

Document Number:

702400559

FIELD INSPECTION FORMLoc ID 336171 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

15 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
243491	WELL	TA	08/03/2021	OW	123-11282	UPRR 50 PAN UT "F" TRUE 1	TA
279671	WELL	TA	05/09/2016	GW	123-23219	VOLCIC 3-27	TA

General Comment:

Location

Overall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	adequate x 2		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Chainlink topped with barb wire		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Chainlink topped with barb wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Chainlink topped with barb wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		

Comment:		Date:	
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Card indicates current calibration		
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	both are exposed at surface		
Corrective Action:		Date:	
Type: Ancillary equipment	# 5		
Comment:	automation		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	bradenhead surface combustion device		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		40.112020,-104.769710
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	75 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Inspector Name: Revas, Robbie

Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Shares containment with crude tank					
Corrective Action:				Date:	

Wells Served By Facilities Above

AirsID

API Number	API Number	AirsID
123-11282		
123-23219		

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 243491 Type: WELL API Number: 123-11282 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: TA, Form 04(OBJ-TA) Doc # 402899760

Corrective Action: _____ Date: _____

BradenHeadDate of Last Brhd Test: 04/22/2022 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: NoneEnd Surf Csg Pressure: --

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 279671 Type: WELL API Number: 123-23219 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: TA, Form 04(OBJ-TA) Doc # 402896071

Corrective Action: _____ Date: _____

BradenHeadDate of Last Brhd Test: 12/01/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 72 Fluid Type: GASEnd Surf Csg Pressure: 1

Comment: _____

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday 5-31-2022 at approximately 1100 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection:</p> <p>Operator: Oxy/Kerr McGee</p> <p>Location name: UPRR 50 Pan UT F True 1</p> <p>API #05-123-11282</p> <p>County: Weld</p> <p>Weather: Clear.</p> <p>Location: Dry.</p> <p>While there, I observed wellsite and tank battery, 2 wells TA at the time of inspection.</p> <p>During this inspection, I observed no compliance issues:</p> <p>See attached photos.</p> <p>No follow up site inspection is needed to ensure that the addressed Compliance issues comply with COGCC rules.</p>	revasr	05/31/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702400560	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5766928