

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/25/2022

Submitted Date:

05/25/2022

Document Number:

702400536

FIELD INSPECTION FORM

Loc ID 318533 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 9 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rwatzman@kpk.com	All Inspections
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241522	WELL	PR	08/01/2018	OW	123-09311	PACE-CONNELLY 1	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	adequate, fading and beginning to peel will need to be replaced in the near future		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>	Date:	

Good Housekeeping:

Type	OTHER		
Comment:	Mechanical issue, Leak around the tubing coming out of the bradenhead just below the master valve		
Corrective Action:	Comply with Rule 608.e: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition.		Date: 06/25/2022

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type			
Comment:			
Corrective Action:		Date:	

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Pump Jack	# 1	Pump jack sitting disassembled in the weeds.			
Bradenhead	# 1	appears plumbed to surface			
Plunger Lift	# 1				

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS

Comment:	See related inspection Doc #693503336 for information concerning shared facilities and equipment.		
----------	---	--	--

Corrective Action:		Date:	
--------------------	--	-------	--

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			
		Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 241522 Type: WELL API Number: 123-09311 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 10/21/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment: <input style="width: 90%;" type="text"/>						
Corrective Action: <input style="width: 90%;" type="text"/>						Date: _____
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday 5/25/2022 at approximately 1130 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Operator: KP Kauffman Location: Pace-Connelly 1 API # 05-123-09311 County: Weld While there, I observed a wellsite, PR at the time of inspection. During this inspection the following possible compliance issues were observed: 608.e Mechanical Issue: Leak around the tubing coming out of the bradenhead just below the master valve, CA date 6-25-2022. See attached photos. Location: muddy, Weather: clear/partly cloudy. I spoke with Mani Silva with KP Kauffman at 1130 hrs. about the Mech. issue and he said he'd get someone out to look at it. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	revasr	05/25/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403059882	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5763425
702400537	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5763417
702400538	leak vid	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5763418