

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/25/2022

Submitted Date:

05/25/2022

Document Number:

702500056**FIELD INSPECTION FORM**Loc ID 333535 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10679Name of Operator: LOGOS OPERATING LLCAddress: 2010 AFTON PLACECity: FARMINGTON State: NM Zip: 87401**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:18 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, General		regulatory@logosresourcesllc.com	All SW field inspections
Rowley, Darren	505-947-4974	drowley@logosresourcesllc.com	All SW field Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214113	WELL	PR	01/29/1958	GW	067-05423	BONDAD 33-9 14	PR
215524	WELL	PR	06/16/2000	GW	067-07129	ALVA SHORT B 1	PR
474316	Domestic Tap	AC	03/26/2020		-	Domestic Tap 18SENW	AC

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos. See inspection document number 700300411 for FLIR report.

Location				
Lease Road:				
Type	Access			
comment:	Gravel access road.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:	Emergency contact listed on well sign, located on north side of dehydrator house.			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	WEEDS			
Comment:	Weeds encroaching produced water tank and location (IMG 08, IMG 09, IMG 13).			
Corrective Action:	Control weeds around equipment and inside containment structure per rule 606.			Date: 06/08/2022
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
Equipment:				
Type: Ancillary equipment	# 4			corrective date
Comment:	Cathodic protector, Electric panel, flow line risers on northeast side of location, telemetry			
Corrective Action:				Date:
Type: Bird Protectors	# 2			
Comment:	Separator vent stack and dehydrator vent stack are screened properly.			
Corrective Action:				Date:
Type: Flow Line	# 4			
Comment:	2" line from well head to separator, 2" line from separator to meter house, 2" line from separator to produced water tank, 1" line from meter house to domestic tap.			
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 1			
Comment:				
Corrective Action:				Date:
Type: Other	# 1			
Comment:	Domestic tap not appearing in COGIS database (IMG 04).			
Corrective Action:	Confirm Form 44 has been submitted or submit Form 44 per rule 1103.b.			Date: 06/24/2022
Type: Bradenhead	# 1			
Comment:	Bradenhead is accessible.			
Corrective Action:				Date:
Type: Dehydrator	# 1			

Comment:	Dehydrator house also contains meter. Oily fluid has impacted floor of dehydrator house, and will begin to impact surface material and impact stormwater runoff (IMG 10). In addition exhaust is producing white smoke and combusted glycol odor.			
Corrective Action:	Remove oily fluid inside dehydrator house per rule 1002. Confirm dehydrator is operating to manufacturers specifications per 608.e.		Date:	06/08/2022
Type: Compressor	# 1			
Comment:	Compressor is enclosed by louvres.			
Corrective Action:			Date:	
Type: Gas Meter Run	# 1			
Comment:	Meter located inside dehydrator house. No gas meter calibration records present (IMG 06).			
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1). Display legible meter calibration record in conspicuous location to comply with rule 430.d.(2).		Date:	06/08/2022

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.106803,-107.870948	
Comment:	Partially buried produced water tank with steel mesh top.					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)	Produced water.	
Other (Capacity)	125 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Metal berm with metal access stairs.			
Corrective Action:				
			Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:			
		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	<u>214113</u>	Type:	<u>WELL</u>	API Number:	<u>067-05423</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>215524</u>	Type:	<u>WELL</u>	API Number:	<u>067-07129</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>474316</u>	Type:	<u>Domestic Tap</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>AC</u>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Compressor generator muffler exhaust is impacting surface material \(IMG 11\).](#)
[No active stormwater erosion or impact is evident anywhere else on location.](#)

Corrective Action: [Remove impacted material per rule 1002.e.](#) Date: 06/08/2022

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Wildlife BMP's appear sufficient, all openings and vents are properly screened.	klinka	05/25/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403060006	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5763630
702500059	Document Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5763628