

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/25/2022

Submitted Date:

05/25/2022

Document Number:

702500057**FIELD INSPECTION FORM**Loc ID 333535 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10749Name of Operator: SIMCOE LLCAddress: 1199 MAIN AVE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:19 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		sjninspections@ikavenergy.co m	All SW field inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214113	WELL	PR	01/29/1958	GW	067-05423	BONDAD 33-9 14	PR
215524	WELL	PR	06/16/2000	GW	067-07129	ALVA SHORT B 1	PR
474316	Domestic Tap	AC	03/26/2020		-	Domestic Tap 18SENW	AC

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

Location			
Lease Road:			
Type	Access		
comment:	Gravel access road.		
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Produced water tank label is deteriorated and not legible (IMG 13).		
Corrective Action:	Install sign to comply with rule 605.h.		Date: 04/22/2022
Emergency Contact Number:			
Comment:	Emergency number listed on sign at location entrance.		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	Material around wellhead is impacted by oily residue (IMG 09).		
Corrective Action:			Date:
Type	WEEDS		
Comment:	Weeds encroaching facility and equipment. Generator muffler is exhausting directly onto dead and dry weeds (IMG 08, IMG 10).		
Corrective Action:	Control weeds to comply with rule 606.		Date: 06/08/2022
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	OTHER		
Comment:	Produced water tank is enclosed by stock panel.		
Corrective Action:			Date:
Equipment:			
Type: Ancillary equipment	# 1		corrective date
Comment:	Lube oil tank near pump jack is over half full, with ~8" of freeboard in secondary containment (IMG 07).		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Domestic Tap		
Corrective Action:			Date:
Type: Deadman # & Marked	# 1		
Comment:	Rig anchor unmarked on southwest side of location.		

Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead is accessible.		
Corrective Action:		Date:	
Type: Flow Line	# 4		
Comment:	2" line from wellhead to separator, 2" line from separator to produced water tank, 3" line from separator to meter house, 1" line from meter house to domestic tap.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Telemetry, electric pump control		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	Separator vent stack is properly screened.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Pump jack enclosed by sound panels.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	BV STEEL		37.106667,-107.870818
Comment:	Partially buried produced water tank. Access hatch enclosed by steel screen.				
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	produced water
Other (Capacity)	21 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Metal berm around produced water tank.			
Corrective Action:			Date:	

Venting:

Yes/No	
--------	--

Inspected FacilitiesFacility ID: 214113 Type: WELL API Number: 067-05423 Status: PR Insp. Status: PRFacility ID: 215524 Type: WELL API Number: 067-07129 Status: PR Insp. Status: PRFacility ID: 474316 Type: Domestic Tap API Number: - Status: AC Insp. Status: AC

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No observed impact of storm water. Storm water controls seem sufficient at time of report.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403060007	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5763631
702500058	Photo Document	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5763629