

**Inspection Photos**  
**Location Name: William Lansdown #1**  
**Location ID: 317613**



**Photo 1 Well head**



**Photo 2 Unused equipment vertical separator**

**Inspection Photos**  
**Location Name: William Lansdown #1**  
**Location ID: 317613**



**Photo 3 Hoz sep**



**Photo 4 riser missing LOTO**



**Location ID: 317613**



**Inspection Photos**  
**Location Name: William Lansdown #1**  
**Location ID: 317613**



**Photo 7 Risers not LOTO**



**Photo 8 Crude oil tank. NPPA placard faded and peeling off.**



**Inspection Photos**  
**Location Name: William Lansdown #1**  
**Location ID: 317613**



**Photo 9 this is a shared road access with OXY operating company.**



**Photo 10 Stained soil in front of well head**



**Inspection Photos**  
**Location Name: William Lansdown #1**  
**Location ID: 317613**



**Photo 11 unused equipment and not LOTO riser**



**Photo 12 Risers not LOTO**

**Inspection Photos**  
**Location Name: William Lansdown #1**  
**Location ID: 317613**



**Photo 13 Road access shared with resident. Stained soil in front of well head**