

Inspection Photos

API: 071-09920

Operator: TWIN BRIDGES RESOURCES LLC

Inspection Date: 5/31/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09920 | Date: 5/31/2022

Inspection Photos



Photo 1. Facing southeast at the entrance of the access road. Sign is posted at entrance.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09920 | Date: 5/31/2022

Inspection Photos



Photo 2. Facing southeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09920 | Date: 5/31/2022

Inspection Photos



Photo 3. The well has been drilled at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09920 | Date: 5/31/2022

Inspection Photos



Photo 4. There is inadequate stormwater controls down gradient and around the cuttings pile. The silt fence is not properly installed or maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09920 | Date: 5/31/2022

Inspection Photos




Photo 5. The straw wattles around the soil pile are not properly staked down. Soils is overtopping the wattles shown at yellow arrow and there is a space between the wattles at red arrow. Stormwater controls need to be installed per good engineering practice.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09920 | Date: 5/31/2022

Inspection Photos



Photo 6. The silt fence is strung across the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09920 | Date: 5/31/2022