

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/31/2022

Submitted Date:

05/31/2022

Document Number:

693700985

FIELD INSPECTION FORMLoc ID 406267 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 93200

Name of Operator: VESSELS OIL & GAS COMPANY

Address: 8435 W 88TH AVE

City: ARVADA State: CO Zip: 80005

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

1 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
Burn, Diana		diana.burn@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240343	WELL	PA	09/16/1996	GW	123-08131	WILLIAM H PELTIER 1	EI

General Comment:

COGCC Environmental Staff conducted an inspection of the plugged and abandoned William H Peltier 1. COGCC observed a monument placed over the well location and five soil vapor points.

COGCC conducted PID/Methane/LEL/CO/O2/H2S screening of the atmosphere with a RKI GX-6000 handheld multi-gas meter. COGCC did not detect VOCs, methane, CO or H2S in the atmosphere. Conditions were cool and slightly breezy.

COGCC screened each soil vapor point, but soil vapor points are not labeled and it is uncertain which COGCC may have screened. Below is a presumed summary based on observed field conditions and a Site Map prepared by AG Wassenaar, Inc. on behalf of Oakwood Homes of Colorado:

VW1-10: 1300 ppm
 VW1-20: 0 ppm
 VW1-30: 100 ppm
 SV-1?: 2900 ppm
 SV-4?: 100 ppm
 SV-5 or 8?: 0-100 ppm
 SV-6 or 10?: 0 ppm

Inspected FacilitiesFacility ID: 240343 Type: WELL API Number: 123-08131 Status: PA Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693700986	William H Peltier 1 Monument (1)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5768072
693700987	William H Peltier 1 Monument (2)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5768073
693700988	William H Peltier 1 looking west	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5768074
693700989	William H Peltier 1 looking south	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5768075
693700990	William H Peltier 1 looking north	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5768076
693700991	William H Peltier 1 looking east	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5768077
693700992	Soil Vapor screening on north side of well	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5768078
693700993	Soil Vapor points located during site visit	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5768079