

## Inspection Photos

Location Name: Semler #2, Herrera #1A, IGE 138, IGE 137

Location ID: 311925



IMG 01  
Semler 2 sign



IMG 02  
Site overview 1/2



**IMG 03**  
Site overview 2/2



**IMG 04**  
MIT



**IMG 05**  
**Herrera 1A sign**



**IMG 06**  
**Herrera 1A wellhead**



**IMG 07**  
**IGE 138 well sign**



**IMG 08**  
**IGE 138 well head**





**IMG 09**  
**IGE 137 well sign**



**IMG 10**  
**IGE 137 wellhead**



**IMG 11**  
**IGE 137 oily fluid**



**IMG 12**  
**Produced water tank**



**IMG 13**  
**Meter house**



**IMG 14**  
**Meter house**



**IMG 15**  
**Meter house**



**IMG 16**  
**Erosion encroaching on wellpad**





**IMG 17**  
Erosion encroaching on well pad



**IMG 18**  
Telemetry



**IMG 19**  
**Unused open ended flow line**



**IMG 20**  
**Unused flow lines**



**IMG 21**  
**Unused flow lines**



**IMG 22**  
**Unused flow line**





**IMG 23**  
**Unused flow line**



**IMG 24**  
**Unused flow lines**



**IMG 25**  
**Photo of Form 21**