

Inspection Photos  
Location Name: Ignacio 33-8 027  
Location ID: 326435



IMG 01  
Well Sign



IMG 02  
Site overview



**Inspection Photos**  
**Location Name: Ignacio 33-8 027**  
**Location ID: 326435**



**IMG 03**  
**Wattles**



**IMG 04**  
**Wattles**

**Inspection Photos**  
**Location Name: Ignacio 33-8 027**  
**Location ID: 326435**



**IMG 05**  
**Rip Rap**



**IMG 06**  
**Well head**



**Inspection Photos**  
**Location Name: Ignacio 33-8 027**  
**Location ID: 326435**



**IMG 07**  
**Vertical Separator**



**IMG 08**  
**Vertical Separator**





**Inspection Photos**  
**Location Name: Ignacio 33-8 027**  
**Location ID: 326435**



**IMG 09**  
**Cathodic Protection**



**IMG 10**  
**Tank Sign**

**Inspection Photos**  
**Location Name: Ignacio 33-8 027**  
**Location ID: 326435**



**IMG 11**  
**Produced water tank**



**IMG 12**  
**Scale corrosion inhibitor sign is deteriorated and NFPA sign is illegible**



**Inspection Photos**  
**Location Name: Ignacio 33-8 027**  
**Location ID: 326435**



**IMG 13**

**Scale corrosion inhibitor sign is deteriorated and NFPA sign is illegible**




**IMG 14**

**Site photo**

**Inspection Photos**  
**Location Name: Ignacio 33-8 027**  
**Location ID: 326435**



**IMG 15**  
**Flow lines**



**IMG 16**  
**Flow line**



**Inspection Photos**  
**Location Name: Ignacio 33-8 027**  
**Location ID: 326435**



**IMG 17**  
**Flow lines**



**IMG 18**  
**Meter houses**

