

Inspection Photos

API: 071-09475

Operator: OGRIS OPERATING LLC

Inspection Date: 6/1/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09475 | Date: 6/1/2022

Inspection Photos



Photo 1. Facing west along the main access road. There has been additional gravel applied along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09475 | Date: 6/1/2022

Inspection Photos



Photo 2. Facing west. The road sides has been regraded and erosion repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09475 | Date: 6/1/2022

Inspection Photos



Photo 3. The slope of the road side was regraded and seeded. A berm was installed at the toe of slope. This area needs to be monitored for stabilization and may require additional BMP's.



Photo 4. A new culvert has been installed with outlet protection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos



Photo 5. Facing northwest near the wellsite. There was a new culvert installed near the location where frequent stormwater issues was observed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09475 | Date: 6/1/2022

Inspection Photos



Photo 6. Facing toward the wellsite.



Inspection Photos



Photo 7. The leak at the shed was repaired and cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09475 | Date: 6/1/2022