

**LASSO OIL & GAS LLC**  
**CONTINENTAL-63S100W 16SWNW**  
**Location # 315156**



Sign missing information. No API #. No EMS contact  
(911) Legal description does not match COGCC records.



Leaking gauge removed and replaced with valve  
with a plug.

**LASSO OIL & GAS LLC**  
**CONTINENTAL-63S100W 16SWNW**  
**Location # 315156**



**2 rods in the ground. Purpose unclear.**



**Unused pipe.**



**LASSO OIL & GAS LLC**  
**CONTINENTAL-63S100W 16SWNW**  
**Location # 315156**




**Unused pipe.**



**Unused pipe.**

# Location # 315156



**Most recent meter calibration on 6-14-2019.**



**LASSO OIL & GAS LLC**  
**CONTINENTAL-63S100W 16SWNW**  
**Location # 315156**



**Marker is knocked over and not brightly colored.**



**South east edge of location.**



**LASSO OIL & GAS LLC**  
**CONTINENTAL-63S100W 16SWNW**  
**Location # 315156**



**Marker not brightly colored.**



**Marker not brightly colored.**



**LASSO OIL & GAS LLC**  
**CONTINENTAL-63S100W 16SWNW**  
**Location # 315156**



**Storm water erosion on south edge of location.**



**Storm water erosion on south edge of location.**

**LASSO OIL & GAS LLC**  
**CONTINENTAL-63S100W 16SWNW**  
**Location # 315156**



**Storm water erosion on south edge of location.**