

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/01/2022

Submitted Date:

06/02/2022

Document Number:

701103172

**FIELD INSPECTION FORM**Loc ID 315156 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10654

Name of Operator: LASSO OIL &amp; GAS LLC

Address: 3021 RIDGE RD #156

City: ROCKWALL State: TX Zip: 75032

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

11 Number of Comments

6 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name     | Phone          | Email                            | Comment         |
|------------------|----------------|----------------------------------|-----------------|
| Rosenberg, Kelly |                | kelly.rosenberg@state.co.us      |                 |
| Thompson, Bud    |                | BLThomps@BLM.gov                 |                 |
| Pesicka, Conor   |                | conor.pesicka@state.co.us        |                 |
| Freeman, Kris    | (254) 717-0435 | kfreeman@31operating.com         |                 |
| Boulger, Levin   | 970-509-0256   | lboulger@31operating.com         |                 |
| , Engineering    |                | dnr_cogccengineering@state.co.us | All engineering |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name    | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 230340      | WELL | PR     | 11/08/2000  | GW         | 103-08000 | CONTINENTAL 2-16 | PR          |

**General Comment:**

COGCC Follow Up Inspection Report Summary

Follow up to 5/23/2022 inspection # 701103142

Corrected action item

- Leaking gauge removed and replaced with valve with a plug.

Follow up to 12/22/2020 inspection # 700404712 and 7/27/2021 inspection # 701101779

Uncorrected action items

- Most recent meter calibration on 6-14-2019.
- Bradenhead access is not present.
- Sign missing information. No API #. No EMS contact (911) Legal description does not match COGCC records.
- Unused equipment on location. Used pipes and cables. 2 rods in the ground purpose unclear.
- Deadmen markers not brightly colored.
- Storm water erosion on south edge of location.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**Overall Good: ☐**Signs/Marker:**

|                    |  |       |            |
|--------------------|--|-------|------------|
| Type               | WELLHEAD   |       |            |
| Comment:           | Sign missing information. No API #. No EMS contact (911) Legal description does not match COGCC records. |       |            |
| Corrective Action: | Install sign to comply with Rule 605.d.  | Date: | 08/31/2021 |

**Emergency Contact Number:**

|                    |                      |             |
|--------------------|----------------------|-------------|
| Comment:           | No EMS contact (911) |             |
| Corrective Action: |                      | Date: _____ |

**Good Housekeeping:**

|                    |   |       |            |
|--------------------|---|-------|------------|
| Type               | UNUSED EQUIPMENT  |       |            |
| Comment:           | Unused equipment on location. Used pipes and cables. 2 rods in the ground. Purpose unclear. |       |            |
| Corrective Action: | Comply with Rule 606  | Date: | 08/14/2021 |

Overall Good: ☐**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

|                          |  |       |                 |
|--------------------------|--|-------|-----------------|
| Type: Bradenhead         | # 1  |       | corrective date |
| Comment:                 | Bradenhead access is not present.  |       |                 |
| Corrective Action:       | Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2). | Date: | 02/01/2021      |
| Type: Gas Meter Run      | # 1  |       |                 |
| Comment:                 | Most recent meter calibration on 6-14-2019.  |       |                 |
| Corrective Action:       | Calibrate gas metering equipment annually to comply with rule 430.d.(1).                       | Date: | 02/01/2021      |
| Type: Deadman # & Marked | # 1  |       |                 |
| Comment:                 | Deadmen markers not brightly colored.  |       |                 |
| Corrective Action:       | Install proper guy line markers per Rule 1003.a  | Date: | 08/14/2021      |

**Venting:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Yes/No             | NO   |       |  |
| Comment:           | Leaking gauge removed and replaced with valve with a plug. |       |  |
| Corrective Action: |  | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

| Inspected Facilities |                |       |      |             |           |         |    |               |    |
|----------------------|----------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 230340         | Type: | WELL | API Number: | 103-08000 | Status: | PR | Insp. Status: | PR |
| Producing Well       |                |       |      |             |           |         |    |               |    |
| Comment:             | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:   |                |       |      |             |           | Date:   |    |               |    |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: [Storm water erosion on south edge of location.](#)Corrective Action: [Install or repair required BMPs per Rule 1002.f.\(2\)C](#)

Date: 08/14/2021

**Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                    | URL   |
|--------------|--------------------------------|---|
| 701103173    | Inspection 701103172 photo log | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5768857">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5768857</a> |