


Caerus Piceance LLC
N36NWB
Location # 334967



Location



location

Caerus Piceance LLC
N36NWB
Location # 334967



Location



**location and Lack of stabilization/ compaction/
degradation**



Caerus Piceance LLC
N36NWB
Location # 334967



Lack of stabilization/ compaction/ degradation



Lack of stabilization/ compaction/ degradation



Caerus Piceance LLC
N36NWB
Location # 334967



Lack of stabilization/ compaction/ degradation



Lack of stabilization/ compaction/ degradation



Caerus Piceance LLC
N36NWB
Location # 334967



Valve leaking



Valve leaking