

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/01/2022

Submitted Date:

06/02/2022

Document Number:

701103174

FIELD INSPECTION FORMLoc ID 315378 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10654

Name of Operator: LASSO OIL & GAS LLC

Address: 3021 RIDGE RD #156

City: ROCKWALL State: TX Zip: 75032

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

3 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Rosenberg, Kelly		kelly.rosenberg@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Freeman, Kris	(254) 717-0435	kfreeman@31operating.com	
Boulger, Levin	970-509-0256	lboulger@31operating.com	
Thompson, Bud		BLThomps@BLM.gov	
, Engineering		dnr_cogccengineering@state.co.us	All engineering

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230738	WELL	PR	11/08/2000	GW	103-08407	CONTINENTAL 3-28	PR

General Comment:

COGCC Follow Up Inspection Report Summary

Follow up to 4/16/2021 inspection # 701500376

Uncorrected action items

- Bradenhead access not present.
 - Most recent meter calibration in June 2019.
 - Stormwater channel runs off the location, then down access road. As the road crosses Willow Creek ~150 ft from the location, the stormwater channel is partially washing out both sides of the road.
- A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Name of access road is faded.		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	911
Corrective Action:	Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	PIT		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 1		
Comment:	Most recent meter calibration in June 2019.		
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1).	Date:	02/01/2021
Type: Bradenhead	# 1		
Comment:	Bradenhead access not present.		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2).	Date:	02/01/2021

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	230738	Type:	WELL	API Number:	103-08407	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Stormwater channel runs off the location, then down access road. As the road crosses Willow Creek ~150 ft from the location, the stormwater channel is partially washing out both sides of the road.

Corrective Action: Install, maintain, or provide documentation of post construction management plan or BMP's.

Date: 06/19/2021

Pits: ☐ NO SURFACE INDICATION OF PIT

Type: <u>Blowdown</u>	Lined: <u>NO</u>	Pit ID:	Lat:	Long:
Reference Point: _____	Other: _____	Length: _____	Width: _____	

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____

Corrective Action

Date: _____

Fencing:

Fencing Type: Wildlife Fencing Condition: _____

Comment: _____

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: _____

Corrective Action

Date: _____

Anchor Trench Present: _____ Oil Accumulation: NO 2+ feet Freeboard: YES

Comment: _____

Corrective Action

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
701103175	Inspection 701103174 photo log	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5769182