

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/01/2022

Submitted Date:

06/02/2022

Document Number:

701103176

FIELD INSPECTION FORM

Loc ID 315373 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10654
Name of Operator: LASSO OIL & GAS LLC
Address: 3021 RIDGE RD #156
City: ROCKWALL State: TX Zip: 75032

Findings:

- 11 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Thompson, Bud		BLThomps@BLM.gov	
Boulger, Levin	970-509-0256	lboulger@31operating.com	
Rosenberg, Kelly		kelly.rosenberg@state.co.us	
Freeman, Kris	(254) 717-0435	kfreeman@31operating.com	
, Engineering		dnr_cogccengineering@state.co.us	All engineering
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230730	WELL	PR	11/08/2000	GW	103-08399	CONTINENTAL 2-21	PR

General Comment:

Follow up to 4/16/2021 inspection # 701500372
Uncorrected action items

- Bradenhead access is not present.
- Most recent meter calibration in June 2019.
- Stormwater channel that enters the location from the uphill side, runs through the location, and exits downhill on the road.

During this inspection the following compliance issues were observed:

- Fence around pit is broken and fallen.
- Weeds covering location and inside of pit.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location			
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911		Date:
Corrective Action:			
Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds covering location and inside of pit.		
Corrective Action:	Comply with Rule 606		Date: 06/30/2022
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PIT		
Comment:	Fence around pit is broken and fallen. See pit section of inspection.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Equipment:			
Type: Deadman # & Marked			# 4
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run			# 1
Comment:			Most recent meter calibration in June 2019.
Corrective Action:			Calibrate gas metering equipment annually to comply with rule 430.d.(1). Date: 02/01/2021
Type: Bradenhead			# 1
Comment:			Bradenhead access is not present.
Corrective Action:			Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2). Date: 02/01/2022
Type: Bird Protectors			# 1
Comment:			
Corrective Action:			Date:

Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 230730 Type: WELL API Number: 103-08399 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing well](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Stormwater channel that enters the location from the uphill side, runs through the location, and exits downhill on the road.

Corrective Action: Install, maintain, or provide documentation of post construction management plan or BMP's.

Date: 06/19/2021

Pits: NO SURFACE INDICATION OF PIT

Type: Blowdown Lined: Pit ID: Lat: Long:

Reference Point: Other: Length: Width:

Lining:

Liner Type: Liner Condition:

Comment: Buried fiberglass tank in pit.

Corrective Action

Date:

Fencing:

Fencing Type: Wildlife Fencing Condition: Inadequate

Comment: Fence around pit is broken and fallen.

Corrective Action

Repair fencing around blowdown pit.

Date: 06/30/2022

Netting:

Netting Type: Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present: Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective Action

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701103177	Inspection 701103176 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5769183