

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/01/2022

Submitted Date:

06/02/2022

Document Number:

690103051

FIELD INSPECTION FORMLoc ID 320406 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10110

Name of Operator: GREAT WESTERN OPERATING COMPANY LLC

Address: 1775 SHERMAN STREET STE 3000

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		cogccinspections@gwogco.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203676	WELL	PR	06/01/2021	GW	001-09236	HSR-EPPINGER 6-1	EG

General Comment:COGCC Engineering Integrity Inspection; Flowline Inspection
Photo uploaded

Inspected Facilities

Facility ID: 203676 Type: WELL API Number: 001-09236 Status: PR Insp. Status: EG

Flowline

#1	Type: Well Site	of Lines
----	-----------------	----------

Flowline Description

Flowline Type: Well Site Size: _____ Material: _____
 Variance: _____ Age: _____ Contents: _____

Integrity Summary

Failures: _____ Spills: _____ Repairs Made: _____
 Coatings: _____ H2S: _____ Cathodic Protection: _____

Pressure Testing

Witnessed: _____ Test Result: _____ Charted: _____

COGCC Rules (check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: Well (HSR-Eppinger 6-1) has been plugged and abandoned; cut and cap operations have been completed. COGCC form 42 notice of start of plugging operations doc #403020805 received 04/19/2022. The wellhead flowline (on location) removed/ AIP. COGCC form 42 notice of flowline pre-abandonment notice doc #402997628 received on 03/29/2022. The on location dump and process flowlines at facility/ battery have been removed. No flowline risers were observed at the (PA) wellhead or facility/ battery areas. The facility/ tank battery has been decommissioned; tanks and equipment have been removed. (1) OOS gas meter run observed on the south side of location; gas gathering line pin flagged. No GWOC were on location at the time of inspection.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
As outlined on COGCC form 19 spill report Doc #403059888 received on 05/25/2022: PDC discovered a reportable release at the HSR Eppinger 6-1 pad near the oil production line. Release clean-up and delineation activities are underway. Historical Release.	maclarej	06/02/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690103052	Location; OOS GMR & fenced excavation/ remediation	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5769437