

FORM  
INSPRev  
X/20

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/25/2022

Submitted Date:

06/02/2022

Document Number:

702800269

### FIELD INSPECTION FORM

Loc ID: 314497    Inspector Name: O'Malley, Anna    On-Site Inspection:     2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 16700  
Name of Operator: CHEVRON USA INC  
Address: 760 HORIZON DRIVE STE 401  
City: GRAND JUNCTION    State: CO    Zip: 81506

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 7    Number of Comments  
1    Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Puechner, Rachel		RPuechner@chevron.com	<a href="#">Decommissioning Advisor Wilson Creek</a>
Olson, Andrew		AndrewOlson@chevron.com	<a href="#">Principle Agent Wilson Creek</a>
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
314497	LOCATION	AC			-	WILSON CREEK UNIT-62N94W 2SWNE	RI

**General Comment:**

On 05/25/2022, Reclamation Specialist O'Malley conducted a follow up inspection to #702800192 at Chevron USA Inc's Wilson Creek Unit-62N94W /2SWNE Location #314497 in Rio Blanco County, Colorado. West Environmental Supervisor, Alex Fischer was also present for the inspection.

The following compliance issues were observed during this inspection:  
- Stormwater: Spoil piles present off site

Refer to the "Location," "Stormwater" and "COGCC Comments" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	At the time of this inspection fencing was present around the perimeter of the wellhead excavation.		
Corrective Action:		Date:	

**Equipment:**

Type: Other	#		corrective date
Comment:	At the time of this inspection the sides of the excavation around the wellhead are gentle enough to allow for wildlife egress.		
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 314497 Type: LOCATION API Number: - Status: AC Insp. Status: RI

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

**Comment:** Previous inspection #702800192 observed erosion control BMPs on the Location are missing or insufficient. Inspector required Operator to install or repair required BMPs per Rule 1002.f by 6/10/22. It was observed in this inspection straw wattles are present along the downslope perimeter of the Location. This corrective action has been addressed. However, spoil piles are present downslope of the wattle throughout the edge of the Location. Soil continues down the hillside ~30 yards from the Location edge causing offsite degradation. Refer to attached email regarding this issue.

Refer to "COGCC Comments" section for additional "STORMWATER COMMENTS"

**Corrective Action:** Comply with 1002.f and remove spoil piles from the hillside downslope of the Location.

Date: 07/02/2022

**Pits:**  NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p><b>STORMWATER COMMENTS</b></p> <p>Previous inspection #702800192 observed BMPs to prevent soil piles potentially contaminated with E&amp;P waste from migrating offsite were absent. Inspector required Operator to comply with Rule 913.b.(5).B.i-v by 5/13/22. It was observed in this inspection that wattles have been installed around the downslope perimeter of 2 soil piles. This corrective action has been addressed.</p>	omalleya	06/02/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702800270	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5769533">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5769533</a>
702800271	Email Correspondence	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5769534">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5769534</a>