

Final Reclamation Inspection

May 19th, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 307211

Inspection Document #: 701900382

SESW Section 25 T5N R68W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Ryan 25-BU
Location ID: 307211



Photo 1. 2021 aerial imagery of the well pad and tank battery.

Inspection Photos
Location Name: Ryan 25-BU
Location ID: 307211



Photo 2. Overview photo of the tank battery taken at ground level from the western edge looking east.

Inspection Photos
Location Name: Ryan 25-BU
Location ID: 307211



Photo 3. Cardinal photos taken from the middle of the tank battery. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Ryan 25-BU
Location ID: 307211



Photo 4. Cardinal photos taken from the middle of the well pad. Left photo facing south, right photo facing west. Note: evidence of drill row seeding and desirable species observed during inspection. Tank battery will remain in process until alfalfa has re-established or crop field has been repurposed and site can be re-inspected.

Inspection Photos
Location Name: Ryan 25-BU
Location ID: 307211



Photo 5. Overview photo of the well pad taken at ground level from the southern edge looking north. Note: well pad does shows stunted alfalfa crop and does not appear consistent with reference area (see photo 6).

Inspection Photos
Location Name: Ryan 25-BU
Location ID: 307211



Photo 5. Reference area.