

Inspection Photos
Location Name: Champlin HER 2-8
Location ID: 320245



Pic 1 tanks



Pic 2 gas meter run separators

Inspection Photos
Location Name: Champlin HER 2-8
Location ID: 320245




Pic 3 stined soil in separator house



Pic 4 trash stored in separator house

Inspection Photos
Location Name: Champlin HER 2-8
Location ID: 320245




Pic 5 trash and stained soil in separator house



Pic 6 Mechanical issue / stained soil by well head

Inspection Photos
Location Name: Champlin HER 2-8
Location ID: 320245



Pic 7 stained soil / mechanical issue / trash stored in motor house

Pic 8 stained soil / mechanical issue / trash stored in motor house

Inspection Photos
Location Name: Champlin HER 2-8
Location ID: 320245



Pic 9 chemical tank leak, stained soil visible on outside of motor house, no containment used on chemical tank(s)



Pic 10 pit

Inspection Photos
Location Name: Champlin HER 2-8
Location ID: 320245



Pic 11 pit

Pic 2 gas meter run, separators