

# Inspection Photos

May 31, 2022

Operator: Caerus Piceance LLC- #10456

Location ID: 334892

Location Name: Shideler-66S92W /32SWNE

Inspection Document #: 702800290

Garfield County, CO

SWNE Section 32 T6S R92W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Shideler-66S92W /32SWNE  
Location ID: 334892



**Photo 1.** Photo taken from the separator at the northeast of the Location shows fence panels completely enclosing an excavation.



**Photo 2.** Photo taken from the separator at the northeast of the Location shows fence panels completely enclosing an excavation. Photo also shows the sides of the excavation are gently sloped and stepped to allow for egress.



Inspection Photos  
Location Name: Shideler-66S92W /32SWNE  
Location ID: 334892



**Photo 3.** Photo taken from the southeast of the Location shows where a guy line anchor has been removed.



Inspection Photos  
Location Name: Shideler-66S92W /32SWNE  
Location ID: 334892



**Photo 4.** Photo taken from the ditch to the east of the Location shows where Noxious salt cedar plants have been removed.



Inspection Photos  
Location Name: Shideler-66S92W /32SWNE  
Location ID: 334892



**Photo 5.** Photo taken from the south of the Location shows interim area shrub interspaces dominated by bare ground and undesirable plant species/weeds.



**Photo 6.** Photo taken from the north of the Location shows where erosion was raked. Erosion continues at the site, as no control measures were implemented to stabilize soils.



Inspection Photos  
Location Name: Shideler-66S92W /32SWNE  
Location ID: 334892



**Photo 7.** Refer to Photo 6 comments.



**Photo 8.** Refer to Photo 6 comments.