

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/31/2022

Submitted Date:

05/31/2022

Document Number:

702400561

**FIELD INSPECTION FORM**

Loc ID 318481 Inspector Name: Revas, Robbie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 14 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	<a href="#">All Inspections</a>
,		dnr_cogccenforcement@state.co.us	
,		rwatzman@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241374	WELL	PR	01/01/2020	OW	123-09163	CLEMENTINE B COBURN B UNIT 1	PR
463438	TANK BATTERY	AC	03/21/2019		-	Clementine Coburn battery	AC

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	adequate, beginning to fade and will need to be replaced in the near future.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	adequate, beginning to fade and will need to be replaced in the near future.		
Corrective Action:			Date:
Type	BATTERY		
Comment:	adequate, beginning to fade and will need to be replaced in the near future.		
Corrective Action:			Date:

Emergency Contact Number:

Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PUMP JACK		
Comment:	hog fence		
Corrective Action:			Date:

**Equipment:**

Type			corrective date
Ancillary equipment	# 4		
Comment:	automation, electric panel and meter box		
Corrective Action:			Date:
Bradenhead	# 1		
Comment:	appears plumbed to surface		
Corrective Action:			Date:
Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:			Date:

Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 3		
Comment:	cards in meter houses indicate that calibration is not current		
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1).		Date: 05/25/2022
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:	See Inspection Doc # 699305089 for related shared facilities and equipment.				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 241374 Type: WELL API Number: 123-09163 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 10/12/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 463438 Type: TANK API Number: - Status: AC Insp. Status: AC

**Producing Well**

Comment: AC

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On Tuesday 5/31/2022 at approximately 1150 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Follow up to inspection Doc # 699305089.                      Operator: KP Kauffman                      Location: Clementine B Coburn B Unit 1                      API # 05-123-09163                      County: Weld                      While there, I observed a wellsite and tank battery, PR at the time of inspection. During this inspection the following possible compliance issues were observed and are delinquent:                      430.d.(1) Gas Meter Calibration: 3 meters not calibrated annually, CA date 5-25-2022. See attached photos.                      Location: Dry, Weather: clear/cloudy.                      A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	revasr	05/31/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403063613	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5766933">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5766933</a>
702400562	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5766929">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5766929</a>