

Location

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	adequate, fading and will need to be replaced in the near future		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	fabricated steel pipe and round stock		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	card in meter box indicates that calibration is not current		
Corrective Action:	Comply with Rule 430	Date:	05/13/2022
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		

Comment:	automation and electric pane		Date:	
Corrective Action:			Date:	
Type: Pump Jack	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Bradenhead	# 1			
Comment:	appears plumbed to surface		Date:	
Corrective Action:			Date:	
Type: Deadman # & Marked	# 2			
Comment:			Date:	
Corrective Action:			Date:	
Type: Prime Mover	# 1			
Comment:	electric motor		Date:	
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:	See Inspection Doc # 702400323 for related shared facilities and equipment.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

Flaring:

Type	
Comment:	
Corrective Action:	
	Date:

Inspected Facilities

Facility ID: 244145 Type: WELL API Number: 123-11938 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 03/29/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday 5-31-2022 at approximately 1225 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Follow up to inspection Doc # 702400323. Operator: KP Kauffman Location name: Conner 21-34 API #05-123-11938 County: Weld Weather: Cloudy/clear Location: Dry. While there, I observed a wellsite and tank battery, PR at the time of inspection. During this inspection, I observed the following possible compliance issue and it is now delinquent: 430 Measurement of Gas: Card in meter box indicates that calibration is not current, CA date 5-13-2022. See attached photos. A follow up site inspection is needed to ensure that the addressed Compliance issues comply with COGCC rules.</p>	revasr	05/31/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403063614	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5766934
702400564	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5766930