

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/06/2022

Submitted Date:

06/07/2022

Document Number:

690103053

FIELD INSPECTION FORM

Loc ID 323007 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		COGCCInspections@Oxy.com	All inspections
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
244628	WELL	TA	04/05/2022	GW	123-12423	DUNKLEE 2	PA
482273	SPILL OR RELEASE	CL			-	Dunklee 2 O SA Facility	EG

General Comment:

[COGCC Engineering Integrity Inspection; Flowline Inspection](#)
[Photo uploaded](#)

Inspected Facilities

Facility ID: 244628 Type: WELL API Number: 123-12423 Status: TA Insp. Status: PA

Facility ID: 482273 Type: SPILL OR API Number: - Status: CL Insp. Status: EG

Flowline

#1	Type: Well Site	of Lines
----	-----------------	----------

Flowline Description

Flowline Type: Well Site Size: 2" Material: Carbon Steel
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: Well (Dunklee 2) has been plugged and abandoned; cut and cap operations have been completed. COGCC form 42 notice of start of plugging operations doc #402956314 received 02/14/2022. The wellhead flowline (on location) has been removed. The on location dump and process flowlines at facility/ battery have been removed. No flowline risers were observed at the (PA) wellhead or facility/ battery areas. The facility/ tank battery has been decommissioned; tanks and equipment have been removed. (1) OOS gas meter run observed on the east side of location. No Oxy or contract personnel were on location at the time of inspection.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
As outlined on COGCC form 19 spill report Doc #403066504 received on 06/03/2022: During tank battery removal activities at the Dunklee 2 O SA Facility, impacted soil was discovered adjacent to the above ground storage tank (AST) and produced water vessel (PWV). The volume of the release is unknown. Assessment activities are ongoing. The facility is being permanently deconstructed.	maclarej	06/07/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690103056	PA well	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5773020
690103057	Excavations at facility; OOS GMR	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5773021