

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/06/2022

Submitted Date:

06/07/2022

Document Number:

690103054

FIELD INSPECTION FORM

Loc ID 317964 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		COGCCInspections@Oxy.com	All inspections
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240263	WELL	SI	07/01/2020	GW	123-08051	DWIGHT SARCHET GAS UNIT 1	PA
273536	WELL	SI		GW	123-22373	HEDGE 24-22	SI
277101	WELL	SI		OW	123-22898	MORNING FRESH 7-22	PA
284223	WELL	SI		OW	123-23774	MORNING FRESH 25-22	PA
317964	LOCATION	AC			-	DWIGHT SARCHET GAS UNIT-63N66W 22SWNE	EG

General Comment:

[COGCC Engineering Integrity Inspection; Flowline Inspection](#)
[Photos uploaded](#)

Inspected Facilities				
Facility ID: <u>240263</u>	Type: <u>WELL</u>	API Number: <u>123-08051</u>	Status: <u>SI</u>	Insp. Status: <u>PA</u>
Facility ID: <u>273536</u>	Type: <u>WELL</u>	API Number: <u>123-22373</u>	Status: <u>SI</u>	Insp. Status: <u>SI</u>
Facility ID: <u>277101</u>	Type: <u>WELL</u>	API Number: <u>123-22898</u>	Status: <u>SI</u>	Insp. Status: <u>PA</u>
Facility ID: <u>284223</u>	Type: <u>WELL</u>	API Number: <u>123-23774</u>	Status: <u>SI</u>	Insp. Status: <u>PA</u>
Facility ID: <u>317964</u>	Type: <u>LOCATION</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>EG</u>

Flowline			
#1	Type: Non-Well Site	of Lines	
<u>Flowline Description</u>			
Flowline Type: <u>Non-Well Site</u>	Size: <u>2"</u>	Material: <u>Carbon Steel</u>	
Variance:	Age:	Contents:	
<u>Integrity Summary</u>			
Failures:	Spills:	Repairs Made:	
Coatings:	H2S:	Cathodic Protection:	
<u>Pressure Testing</u>			
Witnessed:	Test Result:	Charted:	
<u>COGCC Rules(check all that apply)</u>			
<input type="checkbox"/> 1101. Installation and Reclamation <input checked="" type="checkbox"/> 1102. Operations, Maintenance, and Repair <input checked="" type="checkbox"/> 1103. Abandonment			
<u>Comment:</u>	(3) wells have been plugged and abandoned (March 2022); cut and cap work completed. Flowline abandonment (removals) completed (Doc # 403067331/ June 2022). No flowline risers were found at WH or inlet to production equipment/ HHS. (1) well (Hedge 24-22) is SI. Open excavations observed at wellheads and facility/ inlet to HHS. Remediation work in response to historical release(s) in progress. No Oxy or contract personnel were on location at time of inspection.		
<u>Corrective Action:</u>			<u>Date:</u>

COGCC Comments		
Comment	User	Date
As outlined on COGCC form 19 spill report Doc #403058042 received on 05/25/2022: On May 23, 2022, historical soil impacts were discovered following flowline riser removal operations at the Sarchet Dwight GU 1 location. Excavation and assessment activities are ongoing. Site infrastructure has been removed and will not be replaced.	maclarej	06/07/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690103058	Signage at PA well	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5773310
690103059	Fenced excavation at inlet to HHS/ FL riser removal	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5773311