

# Inspection Photos

API: 055-06196

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 6/7/2022



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06196 | Date: 6/7/2022

## Inspection Photos



**Photo 1.** Drone aerial photo facing north along the former access road. The road was not recontoured and reclaimed but continues on past the location. Location shown at red arrow.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06196 | Date: 6/7/2022

## Inspection Photos



**Photo 2.** Facing southwest toward the location which was not recontoured and reclaimed. Previous corrective action was not performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06196 | Date: 6/7/2022

## Inspection Photos



**Photo 3.** Facing southwest down toward the fill slope of the location. The desirable vegetation has not reestablished at the location and there were noxious weeds observed including Red stem filaree, Field bindweed, and Scotch thistle.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06196 | Date: 6/7/2022

## Inspection Photos



**Photo 4.** Facing northwest toward the cut slope of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06196 | Date: 6/7/2022

## Inspection Photos



**Photo 5.** Facing northeast toward the location. The location is not recontoured and reclaimed. Previous corrective action was not performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06196 | Date: 6/7/2022