

Inspection Photos

API: 055-06278

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 6/7/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06278 | Date: 6/7/2022

Inspection Photos



Photo 1. Facing southwest along the former access road. The road was not recontoured and reclaimed. There is erosion occurring along the road and the rock check dams are displaced. Previous corrective action was not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06278 | Date: 6/7/2022

Inspection Photos



Photo 2. Facing southwest along the former access road which was not reclaimed. There are signs of erosion along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06278 | Date: 6/7/2022

Inspection Photos



Photo 3. Facing southwest toward the location which was recontoured and reclaimed. There is desirable vegetation established throughout most of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06278 | Date: 6/7/2022

Inspection Photos



Photo 4. Facing northeast toward the location which was recontoured and reclaimed. There is desirable vegetation established throughout most of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06278 | Date: 6/7/2022

Inspection Photos



Photo 5. South side of the location facing southwest. There are some weeds in this area. Arrow points to Scotch thistle noxious weed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06278 | Date: 6/7/2022