

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

05/25/2022

Submitted Date:

06/02/2022

Document Number:

702800265

FIELD INSPECTION FORM
 Loc ID 314277 Inspector Name: O'Malley, Anna On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|-------|--------------------------|--------------------------------------|
| Heil, John | | john.heil@state.co.us | |
| Puechner, Rachel | | RPuechner@chevron.com | Decommissioning Advisor Wilson Creek |
| Olson, Andrew | | AndrewOlson@chevron.com | Principle Agent Wilson Creek |
| Fischer, Alex | | alex.fischer@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|----------|--------|-------------|------------|---------|---------------------------------|-------------|
| 314277 | LOCATION | AC | | | - | WILSON CREEK UNIT-63N94W 34NWNW | RI |

General Comment:

On 05/25/2022, Reclamation Specialist O'Malley conducted a follow up inspection to #702800201 at Chevron USA Inc's Wilson Creek Unit-63N94W/34NWNW Location #314277 in Rio Blanco County, Colorado. West Environmental Supervisor, Alex Fischer was also present for the inspection.

The following compliance issues were observed during this inspection:

- Excavation lacks proper fencing
- BMPs to prevent E&P waste from migrating off Location missing or insufficient
- Stormwater: BMPs to manage stormwater missing or insufficient

Refer to the "Location" and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

| Type | Area | Volume | | |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|------------------|
| Type | OTHER | | |
| Comment: | <p>Previous inspection #702800201 observed that the area around the well has been excavated. Fence panels were present, but do not completely enclose the excavated area. Inspector required Operator to comply with Rule 913.b.(5).B.i by 5/15/22.</p> <p>It was observed in this inspection that fence panels were stored at the north of the Location and were not in use to enclose the excavation around the wellhead. Inspector acknowledges that at the time of this inspection a contractor was on Location preparing to continue work on the excavated area, therefore fence panels were temporarily decommissioned. Fencing should be reinstalled and continually maintained when work is not occurring. Original corrective action and date remain applicable.</p> | | |
| Corrective Action: | Comply with Rule 913.b.(5).B.i. | | Date: 05/15/2022 |

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

| | | | | | | | | | |
|--------------|--------|-------|----------|-------------|---|---------|----|---------------|----|
| Facility ID: | 314277 | Type: | LOCATION | API Number: | - | Status: | AC | Insp. Status: | RI |
|--------------|--------|-------|----------|-------------|---|---------|----|---------------|----|

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: Previous inspection #702800201 observed excavated soil stored on Location without BMPs to prevent E&P waste from migrating off Location. Inspector required Operator to Comply with Rule 913.b.(5).B.i-v by 5/15/22.

It was observed in this inspection that excavated soil was stored on Location. The Contractor on Location informed the Inspector that the Operator was waiting on delivery of wattles to address the previous corrective action. A berm of uncompacted soil was installed as a temporary control measure to prevent migration of E&P waste off site. Original corrective action and date remain applicable. Additionally, the berm may act as a sediment source/stormwater pollutant. No control measures were present to manage sediment runoff.

Corrective Action: Corrective Action #1: Comply with Rule 913.b.(5).B.i-v. CA Date: 5/15/2022

Date: 05/15/2022

Corrective Action #2: Install or repair required BMPs per Rule 1002.f. CA Date: 6/9/2022

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 403065673 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5768755 |
| 702800266 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5768752 |