

Inspection Photos
Location Name: UPRR 23 PAN AM UT D 4
Location ID: 319981



Pic 1 fencing that goes through lease road



Pic 2 gate that does not have KPK lock on it