

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/09/2022

Submitted Date:

06/09/2022

Document Number:

699504012

FIELD INSPECTION FORM

 Loc ID _____ Inspector Name: _____ On-Site Inspection
 320080 _____ MEDINA, JUSTIN _____ 2A Doc Num: _____
Operator Information:

OGCC Operator Number: 10695

Name of Operator: BEHRENS RESOURCES INC

Address: PO BOX 188

City: DEER TRAIL State: CO Zip: 80135

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments

0 Number of Corrective Actions

 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Hickey, Mike		michael.hickey@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202552	WELL	SI	03/31/2014	GW	001-07957	FARM RANCH EXPLORATION 6	SI

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	weeds unmanaged on location		
Corrective Action:			Date:
Type	OTHER		
Comment:	well is in need of MIT due to length of time well has been shut in.		
Corrective Action:			Date:

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type		#		corrective date
Bradenhead		# 1		
Comment:	plumbed to surface			
Corrective Action:				Date:
Plunger Lift		# 1		
Comment:				
Corrective Action:				Date:
Horizontal Heated Separator		# 1		
Comment:	in shed on location			
Corrective Action:				Date:
Ancillary equipment		# 1		
Comment:	plunger automation			
Corrective Action:				Date:
Bird Protectors		# 1		
Comment:				
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:	unable to inspect due to weed growth			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV FIBERGLASS		
Comment:	75 BBL				
Corrective Action:					Date:

Paint	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	shares containment with oil tank			
Corrective Action:				Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 202552 Type: WELL API Number: 001-07957 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI in need of MIT

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 12/09/2019 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Annual bradenhead test is not current.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<u>This is an orphan well inspection at time of inspection well is in need of annual bradenhead test, and MIT need to be performed on well due to lenght of time well has been SI weeds unmanaged on location, berms need to be repaired around tanks possibly At time of inspection weather conditions were overcast, calm, warm, recent rain</u>	medinaj	06/09/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699504013	inspection pictures	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5775489