

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/03/2022

Submitted Date:

06/09/2022

Document Number:

702500044

## FIELD INSPECTION FORM

 Loc ID: 325731  
 Inspector Name: Klink, Alex  
 On-Site Inspection:   
 2A Doc Num:
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

8 Number of Comments

0 Number of Corrective Actions

 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Operator Information:**

OGCC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Walker, Mandi		mwalker@hilcorp.com	All Inspections SW
Shorty, Priscilla	505-324-5188	pshorty@hilcorp.com	All Inspections SW

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215303	WELL	AC	12/29/1992	OBW	067-06908	MARIE SHIELDS GAS UNIT A 1	AC

**General Comment:**

Inspector Alex Klink on site on 5/17/22 to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

Inspectors Alex Klink and Steve Labowskie returned on 5/31/22 to continue inspection.

Landowner firewood and storage noted in previous inspection have stopped. Stored equipment and vehicles have been removed. Location now covered in wood and bark debris, napweed and mullen becoming established.

Provide COGCC Environmental Supervisor, Alex Fischer, with update on monitoring use of well, sample interval, and collection and use of data.

**Location**

Overall Good:

Emergency Contact Number:

Comment: Emergency number listed on sign at location entrance: 505-324-5170 and 911

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>				
	Type	WELLHEAD		
	Comment:	Wellhead protected by steel post enclosure.		
	Corrective Action:			Date:

<b>Equipment:</b>				
	Type: Flow Line	# 1		corrective date
	Comment:	1 1" flow line is stubbed up near wellhead and is not in use (IMG 07).		
	Corrective Action:			Date:
	Type: Bradenhead	# 1		
	Comment:	Bradenhead is accessible.		
	Corrective Action:			Date:

<b>Venting:</b>				
	Yes/No			
	Comment:			
	Corrective Action:			Date:

<b>Flaring:</b>				
	Type			
	Comment:			
	Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 215303 Type: WELL API Number: 067-06908 Status: AC Insp. Status: AC

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No observed impact of storm water. Storm water controls appear sufficient at time of report.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500049	Photo document	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5776065">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5776065</a>