

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNION-66S96W /33NWSE

Location ID: 335237



Photo #6867 from entrance to location.



Photo #6868 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNION-66S96W /33NWSE

Location ID: 335237



Photo #6869 Vent pipe on tank open ended.



Photo #6870 Loadline open ended.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNION-66S96W /33NWSE

Location ID: 335237



Photo #6872 Insufficient velocity checks in ditch.



Photo #6873 Gully erosion occurring on cut slope.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNION-66S96W /33NWSE

Location ID: 335237



Photo #6875 Gully erosion occurring on cut slope.



Photo #6876 Gully erosion occurring on cut slope.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNION-66S96W /33NWSE

Location ID: 335237



Photo #6877 Gully erosion occurring on cut slope.



Photo #6878 Gully erosion occurring in access road ditch. Insufficient velocity checks in ditch.