

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/09/2022

Submitted Date:

06/10/2022

Document Number:

690103061

FIELD INSPECTION FORM

Loc ID 329643 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		COGCCInspections@Oxy.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
249732	WELL	SI		GW	123-17535	WADDLE 24-5L	SI
249835	WELL	SI	02/01/2021	GW	123-17638	WADDLE 24-4L	PA

General Comment:

COGCC Engineering Integrity Inspection
Off location flowline pressure testing witnessed; Flowline repair/ Return to service
Photos Uploaded

Inspected Facilities

Facility ID: 249732 Type: WELL API Number: 123-17535 Status: SI Insp. Status: SI

Flowline

#1	Type: Non-Well Site	1 of Lines
----	---------------------	------------

Flowline Description

Flowline Type: Non-Well Site Size: 2" Material: Carbon Steel
 Variance: Age: Contents: Multiphase

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: The Waddle 24-4L has been plugged and abandoned; cut and cap work completed. COGCC form 42 notice of start of plugging operations doc #402934392 received 01/24/2022. The associated off location flowline removed; a section of this flowline once shared with Waddle 24-5L. COGCC Inspector met with Oxy contract personnel (Bravo Services) on location. Pressure testing of the Waddle 24-5L off location (wellhead) flowline was in progress. This flowline had recent work completed; T fitting from 24-4L tie in removed and replaced with a 2" sweep. The total length of the flowline is approximately 780' from wellhead to facility.

 The flowline pressure test (hydro) was run for 4 hours and recorded on a data logger (crystal gauge); Starting test pressure of 1560 psi. The test recorded minimal pressure deviation (loss<10%) and adequate stabilization. The tests witnessed is deemed passing/satisfactory per COGCC rule 1104.h.(1)

Corrective Action:

Date:

Facility ID: 249835 Type: WELL API Number: 123-17638 Status: SI Insp. Status: PA

COGCC Comments

Comment	User	Date
As outlined on COGCC form 19 spill report Doc #403068742 received on 06/07/2022: On June 6, 2022, historical soil impacts were discovered following cut and cap operations at the Waddle 24-4L wellhead location. Site infrastructure has been removed and will not be replaced. Excavation and assessment activities are ongoing.	maclarej	06/10/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690103064	PA well' Waddle 24-4L	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5776814
690103065	OLF pressure testing between HHS and WH	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5776815