



# **Refuge to Mallard Production Line Abandonment Photographic Log**

**(May 5th, 2022)**



Photo No 1:

**Description:**  
Location of flowline's northern terminus, on the Refuge S16 Location. Photo facing southeast.



Photo No 2:

**Description:**  
Northern terminus of flowline.



Photo No 3:

**Description:**  
Sampling location  
D90\_RP\_SS\_01, at  
northern terminus of  
flowline.



Photo No 4:

**Description:**  
Location of flowline's  
southern terminus, on  
the Pintail S16  
location. Photo  
facing south.



Photo No 5:

**Description:**  
Southern terminus of flowline.



Photo No 6:

**Description:**  
Sampling location  
D90\_RP\_SS\_02, at  
southern terminus of  
flowline.



Photo No 7:

Description:  
Location of  
D90\_RP\_SS\_BG\_01,  
near the northern  
terminus of the  
flowline. Photo facing  
northeast.



Photo No 8:

Description:  
Close view of  
D90\_RP\_SS\_BG\_01.



Photo No 9:

Description: Location of D90\_RP\_SS\_BG\_02, near the southern terminus of the flowline. Photo facing southwest, toward the Pintail S16 location.



Photo No 10:

Description: Location of D90\_RP\_SS\_BG\_02, near the southern terminus of the flowline. Photo facing northeast, toward the Refuge S16 location.



Photo No 11:

Description:  
Close view of  
D90\_RP\_SS\_BG\_02.