

TEP
Dixon
Location # 311696



location



location

TEP
Dixon
Location # 311696



location




location

TEP
Dixon
Location # 311696



Tank labeling falling off



Valve missing cap/ plug

TEP
Dixon
Location # 311696



Valve missing cap/ plug



Valve missing cap/ plug

TEP
Dixon
Location # 311696



Staining



Debris

TEP
Dixon
Location # 311696



Open cellars



Open cellars



TEP
Dixon
Location # 311696



Open cellars



Open cellars

TEP
Dixon
Location # 311696



Some areas of cut slope have lack of stabilization still. Photo from recent inspection.



Photo from previous inspection

TEP
Dixon
Location # 311696



Some areas of cut slope have lack of stabilization still.



Some areas of cut slope have lack of stabilization still.

TEP
Dixon
Location # 311696



Evidence of cut slope erosion



Cut slope erosion over blankets

TEP
Dixon
Location # 311696



Cut slope erosion over blankets



Lack of stabilization/ compaction/ degradation

TEP
Dixon
Location # 311696



Lack of stabilization/ compaction/ degradation



Lack of stabilization/ compaction/ degradation

TEP
Dixon
Location # 311696



Hard hat upside down in rutting

