

Inspection Photos
Location Name: Comanche Creek 1-14
Location ID: 320324



Pic 1 wellhead / pumpjack, weeds unmanaged, fence needs repair



Pic 2 bradenhead is not plumbed to surface, stained soil

Inspection Photos
Location Name: Comanche Creek 1-14
Location ID: 320324



Pic 3 motor house



Pic 4 stained soil in motor house

Inspection Photos
Location Name: Comanche Creek 1-14
Location ID: 320324



Pic 5 separator



Pic 6 tanks berm is inadequate

Inspection Photos
Location Name: Comanche Creek 1-14
Location ID: 320324



Pic 7 Previous leak from tank has been plugged



Pic 8 unused equipment / risers, separator

Inspection Photos
Location Name: Comanche Creek 1-14
Location ID: 320324



Pic 9 fiberglass tank berms are not adequate

Pic 10 Three gas meter run