

# Inspection Photos

API: 071-08769

Operator: WAPITI OPERATING LLC

Inspection Date: 6/14/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-08769 | Date: 6/14/2022

## Inspection Photos



**Photo 1.** Facing southeast along the main road at the upper part of Lorencito Canyon. The erosion ins this area has been repaired. The culvert was removed and remains on the road side which needs to be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08769 | Date: 6/14/2022



## Inspection Photos



**Photo 2.** This culvert inlet was cleaned out however, the culvert is full of sediment which still needs to be cleaned out. Lat/Long:37.00581,-104.83861. Previous corrective action was not completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08769 | Date: 6/14/2022



## Inspection Photos



**Photo 3.** There is an erosion gully along the road that needs to be repaired and stabilized. Previous corrective action was not completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08769 | Date: 6/14/2022



## Inspection Photos



**Photo 4.** The side of the road is eroded and not stabilized at Lat/Long:36.99952,-104.83425. Erosion head cutting is continuing to occur further back. This area needs to be repaired and stabilized. Previous corrective action not completed. Red arrow points to 4.5 ft. shovel.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08769 | Date: 6/14/2022



## Inspection Photos



**Photo 5.** There was grading performed along the road. The disturbance along the side of the road needs to be seeded and reclaimed. Previous corrective action not completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08769 | Date: 6/14/2022

## Inspection Photos



**Photo 6.** This culvert inlet was cleaned out however, the culvert is full of sediment which needs to be cleaned out. Lat/Long:36.99405,-104.84710.

Previous corrective action not completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08769 | Date: 6/14/2022



## Inspection Photos



**Photo 7.** View of culvert from the previous photo which is full of sediment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08769 | Date: 6/14/2022



## Inspection Photos



**Photo 8.** Facing northeast toward the well site.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08769 | Date: 6/14/2022



## Inspection Photos



**Photo 9.** There are noxious weeds Hounds tongue which has not been controlled. The noxious weeds have already produced seed so the weeds will now need to be bagged and removed. Previous corrective action not completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08769 | Date: 6/14/2022