

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/15/2022

Submitted Date:

06/16/2022

Document Number:

702500085

FIELD INSPECTION FORM

Loc ID 333999 Inspector Name: Klink, Alex On-Site Inspection 2A Doc Num: _____

Operator Information:
OGCC Operator Number: 10749
Name of Operator: SIMCOE LLC
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
15 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		sjninspections@ikavenergy.com	All SW field inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297205	WELL	PR	07/16/2008	GW	067-09602	LILA CUMMINS A 3	PR
297886	WELL	PR	06/28/2021	GW	067-09617	LILA CUMMINS A 4	PR

General Comment:
Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

Location			
Lease Road:			
Type	Access		
comment:	Gravel access road.		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Emergency Contact Number:			
Comment:	Emergency contact listed on well sign. 24 hr contact: 970-247-6916. Emergency contact: 911		
Corrective Action:			Date:
Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds are present in enclosure around pump jacks A3 and A4 (IMG 05, IMG 06).		
Corrective Action:	Control weeds to comply with rule 606.		Date: 07/01/2022
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Pump jacks enclosed by metal fencing.		
Corrective Action:			Date:
Equipment:			
			corrective date
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 2		
Comment:	2 electric prime movers		
Corrective Action:			Date:
Type: Ancillary equipment	# 4		
Comment:	Telemetry and electric panel enclosed in cabinet near separator house, electric meter, 2 pump control panels at pump jacks.		
Corrective Action:			Date:
Type: Flow Line	# 6		
Comment:	2 4" lines from wellhead to separators, 2" line from separator to produced water tank, 4" line from produced water tank, 2 2" lines off gas supply line before separator house,		
Corrective Action:			Date:
Type: Pump Jack	# 2		
Comment:			

Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		
Comment:	3 Vertical heated separators and 3 gas meter runs are all enclosed in one house near produced water tank. Other equipment is associated with Lila Cummins A2 well.		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	Produced water vent stack is properly enclosed.		
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	Bradenheads are accessible.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1		PBV STEEL		37.137128,-107.720093
Comment:	Produced water tank.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Double walled tank.			
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 297205 Type: WELL API Number: 067-09602 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Facility ID: 297886 Type: WELL API Number: 067-09617 Status: PR Insp. Status: PR

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Culverts						
Rip Rap						

Comment: No observed impact of storm water. Storm water controls seem sufficient at time of report.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500086	Photo Doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5781478