

Inspection Photos

Operator: Hilcorp Energy
API: 067-09374
Date: 6/1/2022



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Revgetation is progressing largely with western wheatgrass and sand dropseed.



Photo 3. View of the northern project area from the northeastern corner facing westward.



Photo 4. View of reference area comprised of gambel oak shrubland with Indian ricegrass, yucca, snakeweed, squirreltail, and *chaetopappa ericioides*.