

# Inspection Photos

Operator: Hilcorp Energy  
API: 067-08641  
Date: 6/1/2022



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Revgetation is progressing largely with western wheatgrass, purple threeawn, and rubber rabbitbrush.





Photo 3. View of the southern project area from the southeastern corner facing westward.



Photos 4/5. View of erosional channeling within the northern fill slope, approximately 12-18 wide and deep needing stabilization.





Photo 6. View of reference area comprised of gambel oak shrubland with Indian ricegrass, yucca, snakeweed, squirreltail, and *chaetopappa ericioides*.