

**Inspection Photos**  
**Operator: Hilcorp Energy**  
**API: 067-09069**  
**Date: 6/1/2022**



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Revgetation is progressing largely with western wheatgrass, smooth brome, crested wheatgrass, and rubber rabbitbrush.



Photo 3. View of the western project area from the northwestern corner facing southward.



Photo 4. View of erosional channel with cobble placed in the northern project area (approximately 2-3ft wide and deep). Erosional channeling continues here, around cobble rocks and down-slope.



Photo 5. View of another erosional channel forming within the northeastern portion of the project area (approx. 1-2ft wide and deep).



Photo 6. View of reference area comprised of gambel oak shrubland with Indian ricegrass, yucca, snakeweed, squirreltail, and *chaetopappa ericioides*.