


Inspection Photos  
Location Name: Davis 2-5  
Location ID: 326465




IMG 01  
Well sign



IMG 02  
Site overview




**IMG 03**  
**Unused flow line**



**IMG 04**  
**Trash near pump jack prime mover**





IMG 05

Gas meter calibration out of date



IMG 06

Unused stock panel near produced water tanks





**IMG 07**


**Unused flow line near separator**



**IMG 08**

**Unused flow line near separator**





IMG 09

Trash near compressor house



IMG 10

Rig anchor not secured





IMG 11

Rig anchor not secured



IMG 12

Rig anchor not secured



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources