

Inspection Photos
Location Name: Kendrick 3-31
Location ID: 326463



IMG 01
Well sign



IMG 02
Location overview



IMG 03

Muffler exhaust has begun to impact material