


Inspection Photos  
Location Name: Kendrick 3-6  
Location ID: 326462



IMG 01  
Well sign



IMG 02  
Location overview



**IMG 03**

**Electrical conduit**



**IMG 04**

**Muffler has begun impacting material**





**IMG 05**  
**Electrical conduit**



**IMG 06**  
**Rig anchor not secured**





**IMG 07**

**Trash on east edge of location**



**IMG 08**

**Trash near rig anchor on southwest corner of location**





**IMG 09**

**Lube oil with no spill protection**