

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

06/16/2022

Submitted Date:

06/16/2022

Document Number:

702500094

FIELD INSPECTION FORM
 Loc ID 326161 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

15 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Shorty, Priscilla	505-324-5188	pshorty@hilcorp.com	All SW filed inspections
Labowskie, Steve		steve.labowskie@state.co.us	
Walker, Mandi		mwalker@hilcorp.com	All SW field inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215974	WELL	PR	04/03/1991	GW	067-07580	HUBER-DOBBINS 1-31	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

Location

Lease Road:			
Type	Access		
comment:	Compacted gravel access road		
Corrective Action		Date:	

Overall Good: ☐

Emergency Contact Number:			
Comment:	Emergency contact listed on well sign.		
Corrective Action:		Date:	

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:				
Type	PUMP JACK			
Comment:	Pump jack is enclosed by stock panels.			
Corrective Action:		Date:		

Equipment:				corrective date
Type: Prime Mover	# 1			
Comment:	Gas powered prime mover			
Corrective Action:		Date:		
Type: Ancillary equipment	# 1			
Comment:	Telemetry			
Corrective Action:		Date:		
Type: Deadman # & Marked	# 4			
Comment:	3 of 4 rig anchor markers not secured properly (IMG 03, IMG 04, IMG 05).			
Corrective Action:	Install proper guy line markers per Rule 1003.a			Date: 07/02/2022
Type: Bird Protectors	# 1			
Comment:	Separator vent stack screened properly.			
Corrective Action:		Date:		
Type: Pump Jack	# 1			
Comment:				
Corrective Action:		Date:		
Type: Vertical Heated Separator	# 1			
Comment:				
Corrective Action:		Date:		
Type: Other	# 1			

Comment:	Pump jack lube oil.		
Corrective Action:		Date:	
Type: Flow Line	# 5		
Comment:	2 3" lines from wellhead to separator, 1" line from separator to flow line, 3" line from separator to off location, 4" line from separator to off location.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead is accessible.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 215974	Type: WELL	API Number: 067-07580	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Compaction	Pass					
Berms	Pass					run off berm
		Compaction	Pass			
		Gravel	Pass			

Comment: [No observed impact of storm water. Storm water controls seem sufficient at time of report.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500099	photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5782516