

Inspection Photos

ID: 412161

Operator: WAPITI OPERATING LLC

Inspection Date: 6/14/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

ID:412161 | Date: 6/14/2022

Inspection Photos



Photo 1. Facing northeast at the disturbance along the gathering pipeline at Lat/Long:37.05440,-104.76614. This area has been reseed however, soils are not stabilized and are susceptible to erosion.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

ID:412161 | Date: 6/14/2022

Inspection Photos



Photo 2. Facing southwest along the pipeline disturbance. The disturbed soils are susceptible to erosion due to seep conditions and lack of stabilization until vegetation establishes.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:412161 | Date: 6/14/2022

Inspection Photos



Photo 3. Facing southwest along the pipeline disturbance. The disturbed soils are susceptible to erosion due to seep conditions and lack of stabilization until vegetation establishes.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:412161 | Date: 6/14/2022

Inspection Photos



Photo 4. Facing toward the VPRC CENTRAL FACILITY UNIT C-3.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:412161 | Date: 6/14/2022