

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/14/2022

Submitted Date:

06/14/2022

Document Number:

701005216

FIELD INSPECTION FORM

Loc ID 321651 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 17180
Name of Operator: CITATION OIL & GAS CORP
Address: 14077 CUTTEN RD
City: HOUSTON State: TX Zip: 77069

Findings:

- 7 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Redweik, Bob	(281) 891-1550	bredweik@cogc.com	
Rogers, Bob	719-767-8851	brogers@cogc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207678	WELL	PR	06/02/1986	OW	017-06613	MPU 24-28	PR

General Comment:

[Routine Inspection](#)

Location

Lease Road:

Type	Access				
comment:	Gravel road through farm ground				
Corrective ActionL				Date:	

Overall Good:

Signs/Marker:

Type	WELLHEAD				
Comment:	Lease sign by unit				
Corrective Action:				Date:	

Emergency Contact Number:

Comment:					
Corrective Action:				Date:	

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

					corrective date
Type: Pump Jack	# 1				
Comment:	Sentry 320				
Corrective Action:				Date:	
Type: Prime Mover	# 1				
Comment:	Electric motor				
Corrective Action:				Date:	
Type: Deadman # & Marked	# 4				
Comment:					
Corrective Action:				Date:	
Type: Ancillary equipment	# 2				
Comment:	Electric panel and cathodic rectifier				
Corrective Action:				Date:	

Venting:

Yes/No					
Comment:					
Corrective Action:				Date:	

Flaring:

Type					
Comment:					

Corrective Action:

Date:

Inspected Facilities

Facility ID: 207678 Type: WELL API Number: 017-06613 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Central tank battery for \(MPU Section 27\) 2400' E @ 38.880680/-102.770260](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701005217	Location photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5783289