

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/17/2022

Submitted Date:

06/19/2022

Document Number:

701005251

FIELD INSPECTION FORM

Loc ID 304746 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10112
 Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
 Address: 5057 KELLER SPRINGS RD STE 650
 City: ADDISON State: TX Zip: 75001

Findings:

- 12 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|---------------|----------------|---------------------------------|---------|
| Jones, Greg | (970) 630-3909 | greg.jones@ownresources.com | |
| Beard, Alyssa | | regulatory@foundationenergy.com | |
| Dolezal, Pat | (970) 332-3585 | pat.dolezal@ownresources.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 273987 | WELL | PR | 02/28/2005 | GW | 125-08938 | SHAY 13-8 | PR |

General Comment:

[Routine Inspection](#)

| Location | | | |
|--|---|--------|-----------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Dirt road through pasture | | |
| Corrective Action: | | Date: | |
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Metal sign by water tank. Update stickers to current operator | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Lease sign by wellhead. Update stickers to current operator | | |
| Corrective Action: | | Date: | |
| Emergency Contact Number: | | | |
| Comment: | | | Date: _____ |
| Corrective Action: | | | |
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Metal panels around wellhead | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | Metal panels around meter shed and VGS | | |
| Corrective Action: | | Date: | |
| Type | LOCATION | | |
| Comment: | Wire fence around location | | |
| Corrective Action: | | Date: | |
| Equipment: | | | |
| Type: Gas Meter Run | # 1 | | corrective date |
| Comment: | Meter run 490' south of wellhead | | |
| Corrective Action: | | Date: | |
| Type: Vertical Separator | # 2 | | |
| Comment: | 1-Vertical gas separator in fiberglass shed 1-Vertical gas separator 50% buried by meter shed 490' S | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|--|--|-------|
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Ancillary equipment | # 2 | | |
| Comment: | Telemetry equipment at meter shed 490' south of wellhead | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|----------------------------------|----------|----------------|---------|-----------------------|
| PRODUCED WATER | 1 | OTHER | PBV FIBERGLASS | | 39.896100,-102.219820 |
| Comment: | Fiberglass water tank 50% buried | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | |
| Other (Content) | |
| Other (Capacity) | 210bbbls |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|--|-------|
| Yes/No | | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Inspected Facilities

Facility ID: 273987 Type: WELL API Number: 125-08938 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Meter run is 490' S of wellhead](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | Compaction | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------|---|
| 701005252 | location photo | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5783296 |