



Overview of WC20 Location ID 314509



Equipment at the wellhead has been removed



Area has been repaired and waddles have been repaired or replaced to control sediment migration.







Area has been repaired and waddles have been repaired or replaced to control sediment migration





Anchor was removed