

# Inspection Photos

ID: 442224

Operator: OXY USA INC

Inspection Date: 6/16/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing southeast. There has been disturbance along the flowline from the Compressor to the meter station. There is a pile of sand fill material that will need to be removed. All soils will need to be replaced, reclaimed, and stabilized.



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

442224 | Date: 6/16/2022



## Inspection Photos



**Photo 2.** Facing back to the northwest along the flowline disturbance. All soils will need to be replaced, reclaimed, and stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

442224 | Date: 6/16/2022



## Inspection Photos



**Photo 3.** The flowline crossed the road at this point. The orange safety fence is not maintained and there is a large excavated I the road way.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

442224 | Date: 6/16/2022



## Inspection Photos



**Photo 4.** Facing south toward the Koscove #1 wellsite. There has been disturbance in this area that needs to be reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

442224 | Date: 6/16/2022



## Inspection Photos



**Photo 5.** Facing east toward the flowline disturbance between the meter station and compressor. All soils will need to be replaced, reclaimed, and stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

442224 | Date: 6/16/2022



## Inspection Photos



**Photo 6.** There are areas of disturbance caused by equipment that will need to be reclaimed and stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

442224 | Date: 6/16/2022



## Inspection Photos



**Photo 7.** Facing west toward the flowline disturbance between the meter station and compressor. All soils will need to be replaced, reclaimed, and stabilized.



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

442224 | Date: 6/16/2022



## Inspection Photos



**Photo 8.** There are noxious weeds along the road side and along the flowline areas. Diffuse knapweeds is shown at red arrows and needs to be controlled soon to prevent seed dispersal.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

442224 | Date: 6/16/2022



## Inspection Photos



**Photo 9.** Facing northeast toward the meter station. Diffuse knapweeds is shown at red arrows and needs to be controlled soon to prevent seed dispersal.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

442224 | Date: 6/16/2022



## Inspection Photos



**Photo 10.** There are still degraded wattles on the cut slope that need to be removed. There are noxious weeds in this area that need to be controlled.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

442224 | Date: 6/16/2022



## Inspection Photos



**Photo 11.** Facing southeast toward the meter station. Diffuse knapweeds is shown at red arrows and needs to be controlled soon to prevent seed dispersal.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

442224 | Date: 6/16/2022