

Inspection Photos

API: 055-06068

Operator: OXY USA INC

Inspection Date: 6/16/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06068 | Date: 6/16/2022

Inspection Photos



Photo 1. Facing southwest at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06068 | Date: 6/16/2022

Inspection Photos



Photo 2. Facing northwest toward the reclaimed area at the northwest side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06068 | Date: 6/16/2022

Inspection Photos



Photo 3. There are some displaced straw wattles at the spring area at the northwest side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06068 | Date: 6/16/2022

Inspection Photos



Photo 4. 2015 aerial image of the well site and compressor in the upper right of photo. The red X in the lower left of photo is the associated facility along the County road shown in the next two photos.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06068 | Date: 6/16/2022

Inspection Photos



Photo 5. Facing southeast toward the associated facility adjacent to CR 562.

Lat/Long: 37.689083, -105.219413.

There are noxious weeds in this area that need to be controlled.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06068 | Date: 6/16/2022

Inspection Photos



Photo 6. Facing south at the associated facility. This area is not establishing desirable vegetation and needs to be reseeded. There are numerous noxious weeds in this area that need to be controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06068 | Date: 6/16/2022